


Tastgerät MODULATOR



25 Hz input source is unknown, whether provided by a tuning fork or a R/C oscillator?

FIG. 23
ELEPHANT RADAR ON ROMO.

X shows incorrect interconnection